



Photo 1. *View of sand fencing*



Photo 3. *Typical washout damage (back of dune platform) from TS Matthew, standing at Sta. 101+00 looking east*



Photo 2. *View of sand fencing*



Photo 4. *Typical washout damage (back of dune platform) from TS Matthew, standing at Sta. 138+00 looking northeast*



Photo 5. Typical washout damage (back of dune platform) from TS Matthew, standing at Sta. 150+00 looking southeast



Photo 7. View of back of dune platform and back berm, standing at Sta. 150+00 looking east



Photo 6. View of back of dune platform and back berm, standing at Sta. 150+00 looking west



Photo 8. View of marsh platform at Sta. 150+00 looking northeast



Photo 9. View of dune platform and beach at Sta. 166+00 (camp) looking west. Photo date: October 8, 2004 (as TS Matthew approaches)



Photo 11. View of washout in dune platform from TS Matthew at Sta. 166+00 (camp) looking northwest



Photo 10. View of washout in dune platform from TS Matthew at Sta. 166+00 (camp) looking west



Photo 12. View of dune platform and beach, standing on top of dune at Sta. 166+00 looking east



Photo 13. View of beach, standing on top of dune platform at Sta. 166+00 looking south (tide: appx. 1.0' NAVD)



Photo 15. View of beach, standing at Sta. 165+50 looking west (tide: appx. 1.0' NAVD)



Photo 14. View of washout in dune platform from TS Matthew, standing on the beach at Sta. 165+50 looking north



Photo 16. View of beach, standing at Sta. 165+50 looking east (tide: appx. 1.0' NAVD)



Photo 17. View of dune and beach erosion (foreground) and beach fill/dune repair operations (background), standing at Sta. 176+00 looking east



Photo 18. View of beach fill and discharge pipe at Sta. 191+50 looking south



Photo 19. View of beach fill, discharge pipes, and y-valve used to split the dredge material flow (standing at Sta. 191+50 looking southeast)



Photo 20. View of beach fill, discharge pipes, and y-valve used to split the dredge material flow (standing at Sta. 191+50 looking east)



Photo 21. *View of beach fill and discharge pipes at Sta. 191+50 looking south*



Photo 23. *View of beach fill and dike construction for dune repair at Sta. 191+50 looking southwest*



Photo 22. *View of beach fill and south discharge pipe, standing on north discharge pipe at Sta. 191+50 looking south*



Photo 24. *View of beach fill and dike construction for dune repair, standing on north discharge pipe at Sta. 191+50 looking west*



Photo 25. View of beach fill and south discharge pipe, standing on north discharge pipe at Sta. 191+50 looking south



Photo 27. View of beach past the east end of the project, standing at Sta. 205+50 looking east



Photo 26. View of dune platform at Sta. 191+50 looking north



Photo 28. View of beach past the east end of the project, standing at Sta. 220+00 looking east